



KEY:		
	7 = Exemplary Standard	87-100%
	6 = High Standard	75-86%
	5 = Basic Standard	65-74%
	3 = Improvement Required	50-64%
	0 = Significant Improvement Required	0-49%

Supply Chain Partner	Risk Assessment & Method Statements			Site Tidiness	PPE	Worker Involvement	Safety Adviser Visits	Safety Management Attendance at Safety Review and H&S Action Group		Works Equipment Record	Safe2Start	Max Poss Score	Total	Score %
	Prod	Communicate	Comply					R	AG					
Briggs & Forrester Eng Services Ltd.	5	5	5	7	5	5	6	5	5	5	6	77	59	76.62
Structural Stairways	5	5	5	6	5	5	6	5	5	5	6	77	58	75.32
Haslemere Construction Ltd	5	5	5	6	5	5	6	5	5	5	5	77	57	74.03
Raphael Contracting	5	5	5	6	5	5	6	5	5	5	5	77	57	74.03
Alumet Systems (UK) Ltd.	5	5	5	6	5	5	6	5	5	5	5	77	57	74.03
Bellwood Interiors Limited	5	5	5	6	3	5	6	5	5	5	6	77	56	72.73
FBS Construction	5	5	5	6	5	5	0	5	5	5	5	77	51	66.23

Key: Target Actions 1 Reportable accident/significant incident within the last 12 months  
 2 or more Reportable accident/significant incident within the last 12 months

Supply Chain Distribution: Director responsible for project, Contracts Manager, Health and Safety Advisor, Supervisor