



KEY:	7 = Exemplary Standard	87-100%
	6 = High Standard	75-86%
	5 = Basic Standard	65-74%
	3 = Improvement Required	50-64%
	0 = Significant Improvement Required	0-49%

Supply Chain Partner	Risk Assessment & Method Statements			Site Tidiness	PPE	Worker Involvement	Safety Adviser Visits	Safety Management Attendance at Safety Review and H&S Action Group		Works Equipment Record	Safe2Start	Max Poss Score	Total	Score %
	Prod	Communicate	Comply					R	AG					
Bellwood Interiors Limited	6	6	6	6	3	6	6	5	5	5	6	77	60	77.92
Briggs & Forrester Eng Services Ltd.	5	5	5	6	5	5	6	5	5	5	5	77	57	74.03
Roles Broderick Roofing	5	5	5	6	5	5	6	5	5	5	5	77	57	74.03
Haslemere Construction Ltd	5	5	5	6	5	5	5	5	5	5	5	77	56	72.73
Raphael Contracting	5	5	5	5	5	5	N/A	5	5	5	5	70	50	71.43
Alumet Systems (UK) Ltd.	5	5	5	6	3	5	6	5	5	5	5	77	55	71.43
Alltech Roofing	5	5	5	6	3	5	6	5	5	5	5	77	55	71.43
MACT Scaffolding Limited	5	5	5	6	3	5	0	5	5	5	5	77	49	63.64

Key: **Target Actions** 1 Reportable accident/significant incident within the last 12 months
 2 or more Reportable accident/significant incident within the last 12 months

Supply Chain Distribution: Director responsible for project, Contracts Manager, Health and Safety Advisor, Supervisor